

Baltimore SSO

Site Investigation Report

FM Initials: DE

Project: 19 Moore's Run

Site Name:	19_119S	Monitor Series:	4000 WR	Monitor S/N:	1118	Manhole #:		Investigation Information: Upstream Input: (L/S, P/S) DNI Upstream Manhole: Downstream Manhole: Depth of Flow: 3" + - 0.38 Description of Site Hydraulics: FAIRLY SMOOTH, ELBOW IN MANHOLE
Address / Location:	5411 Glenoak Ave	Map Page #:		Map Grid #:				
		Pipe Height:	17.13"	Pipe Width:	17.13"			
		IP Address:	CDPD					
Access:	Drive	GPS Coords:	N DD.dddd 39 21.462		W DD.dddd 76 32.891			
Date/Time of Investigation:	2/28/2006 0:00							

Access Map

Plan View

Manhole Information:	
Manhole Depth:	18.6'
Manhole Material / Condition:	BRICK / FAIR
Active Drop Connections?	No
System Character:	
<input checked="" type="checkbox"/>	Residential
<input type="checkbox"/>	Commercial
<input type="checkbox"/>	Industrial
Notes: Pipe configuration changed from pre-construction site. Flow elbows in manhole instead of straight through.	
Legend:	
	Cast Iron Flap Valve
	Sensor Location
N.T.S.- Not to scale	

Elevation

Top View

The monitoring period ended as of February 28th 2007.