

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 405 Whittington Ave

Basin: **HS15**

Segment (US : DS): **12528:2570**


Intensity: **Medium**

Drainage Area (SF): **25**

Surface: **Paved**

Comments:

QC Comments: confirm where cleanout defect is - possibly above grade and 0 drainage area - EE



Cleanout, Missing/Broken Cap

Address: 847 Third St

Basin: **HS62**

Segment (US : DS): **2309:2308**

Intensity: **High**

Drainage Area (SF): **10**

Surface: **Unpaved**

Comments:

QC Comments: Need close up verifying defect -verify/reasses grade and drainage

