

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Defective

Address: 103 Clarkson St

Basin: **HS15**

Segment (US : DS): **11089:2603**


Intensity: **High**

Drainage Area (SF): **10**

Surface: **Unpaved**

Comments:

QC Comments: Need close up that confirms defect



Cleanout, Defective

Address: 314 Cedar St

Basin: **HS15**

Segment (US : DS): **1463:1462**

Intensity: **Low**

Drainage Area (SF): **30**

Surface: **Unpaved**

Comments:

QC Comments: retake close up without smoke for verification

