

Sheet 88      **Surveyor's Name** Brian Kauppenin      **Certificate Number** U-218-070300218      **Date** 20241220  
**System Owner**      **Survey Customer**      **Time** 09:22  
**Drainage Area**      **Locality/City Name** Tulsa  
**P.O. No**      **Location (No. & Name)** 3130 S 121st E Ave  
**Further Location Details**      **Inspection Level** Level 2  
**Outgoing Rim to Invert** 7.8 ft      **Outgoing Grade to Invert** 7.7 ft      **Rim to Grade** 0.1 ft  
**Use of Sewer** Sanitary      **Year Laid**      **Year Rehabilitated**      **Media Label**  
**Purpose** Sewer System Evaluation Survey      **Sewer Category**  
**Pre-Cleaning** No Pre-Cleaning      **Date Cleaned**      **Weather**  
**Location Code** Yard      **Potential for Runoff**      **Evidence of Surcharge** Yes  
**Access Point Type** Manhole      **Coordinate System**  
**Northing**      **Easting**      **Elevation**      **Accuracy of GPS**  
**Inspection Status** Remote Inspection  
**Additional Information** No chimney  
**Node Surface Types**

**Concrete Pavement** ☐      **Concrete Collar** ☐      **Asphalt** ☐      **Grass / Dirt** ☒      **Gravel** ☐      **Other** ☐

**Cover**

**Cover Shape** Circular      **Cover Bearing Surface Diameter Width**  
**Cover Size** 23.3 in      **Cover Bearing Surface Diameter** 23.0 in  
**Cover Size Width**      **# Vent Holes**  
**Cover Material** Cast Iron      **Vent Hole Diameter**  
**Cover Frame Fit** Good  
**Cover Type**  

<input checked="" type="checkbox"/> <b>Solid</b>	<input type="checkbox"/> <b>Bolted</b>
<input type="checkbox"/> <b>Vented/Slots</b>	<input type="checkbox"/> <b>Locking</b>
<input type="checkbox"/> <b>Gasketed</b>	<input type="checkbox"/> <b>Lamphole</b>
<input type="checkbox"/> <b>Hatch Single</b>	<input type="checkbox"/> <b>Inner Cover</b>
<input type="checkbox"/> <b>Hatch Double</b>	

**Cover Condition**  

<input checked="" type="checkbox"/> <b>Solid</b>	<input type="checkbox"/> <b>Missing</b>
<input type="checkbox"/> <b>Cracked</b>	<input type="checkbox"/> <b>Corroded/Pitted</b>
<input type="checkbox"/> <b>Broken</b>	<input type="checkbox"/> <b>Bolts Missing</b>
<input type="checkbox"/> <b>Restraint Missing</b>	
<input type="checkbox"/> <b>Restraint Defective</b>	

**Cover Insert**

**Cover Insert Type** None

**Cover Insert Condition**

<input type="checkbox"/> <b>Solid</b>	<input type="checkbox"/> <b>Leaking</b>
<input type="checkbox"/> <b>Poorly Fitting</b>	<input type="checkbox"/> <b>Corroded</b>
<input type="checkbox"/> <b>Cracked/Torn/Holes</b>	<input type="checkbox"/> <b>Insert Fell</b>

Sheet 88

Survey Date 20241220

P.O. No

Location (No. &amp; Name) 3130 S 121st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**☐ Sound☐ Cracked☐ Broken☐ Corroded/Pitted/Worn☐ Leaking☐ Poor Installation**Frame**

Frame Material Cast Iron

Frame Bearing Surface Width 0.8 in

Frame Bearing Surface Depth 1.0 in

Frame Clear Opening Diameter 21.8 in

Frame Offset Distance 0.0 in

Frame Depth

Frame Seal Inflow None

**Frame Condition**☒ Sound☐ Cracked☐ Broken☐ Missing☐ Corroded/Pitted/Worn☐ Coated**Frame Seal Condition**☒ Sound☐ Cracked☐ Broken☐ Loose/Not Attached☐ Offset**Chimney**

Chimney Material 1 Other

Chimney Material 2

Chimney Clear Opening

Chimney Depth 0.0 in

Interior Chimney Coating/Liner None - No Coating

Exterior Chimney Coating/Liner

Chimney I/I

**Cone**

Cone Type Conical centered

Exterior Cone Coating/Liner

Interior Cone Coating/Liner

Cone Depth 3.5 in

Cone Material Brick

**Wall**

Wall Diameter 1 48

Wall Diameter 2

Wall Material Brick

Wall Depth 7.3 in

Interior Wall Coating/Liner Cementitious

Exterior Wall Coating/Liner

**Bench**

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Concrete (non-reinforced)

Channel Type Concrete (non-reinforced)

Channel Exposure F

Channel Installed Y

**Step**

# Steps 4

Step Material Metal

Sheet 88

Survey Date 20241220

P.O. No

Location (No. &amp; Name) 3130 S 121st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	7.8	O	VCP	C	8		D	S	GR	Auto Pipe 65B
	Mainline		Comments								
2	12	7.7	I	VCP	C	8		S	S	GR	Auto Pipe 66B
	Mainline		Comments								
3	3	7.7	I	VCP	C	8		D	S	GR	Auto Pipe 67B
	Mainline		Comments								

**Observations**

Observations												
Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference	
7.4 ft		B	DSF				5			12	12	360-0.0
	Remarks											