

Sheet 1362 Surveyor's Name Caleb Lyda Certificate Number P0053047-032025 Date 20250715
System Owner Survey Customer Time 11:54
Drainage Area Locality/City Name Tulsa
P.O. No Location (No. & Name) 12971 E 32nd St
Further Location Details Neither side of home has a gate had to enter through garage Inspection Level Level 2
Outgoing Rim to Invert 6.8 ft Outgoing Grade to Invert 6.8 ft Rim to Grade 0.0 ft
Use of Sewer Sanitary Year Laid Year Rehabilitated Media Label
Purpose Sewer System Evaluation Survey Sewer Category
Pre-Cleaning No Pre-Cleaning Date Cleaned Weather
Location Code Yard Potential for Runoff Evidence of Surge Yes
Access Point Type Manhole Coordinate System WGS 1984
Northing 36.116 Easting -95.8294 Elevation Accuracy of GPS
Inspection Status Remote Inspection
Additional Information No chimney
Node Surface Types

Concrete Pavement ☐ Concrete Collar ☐ Asphalt ☐ Grass / Dirt ☒ Gravel ☐ Other ☐

Cover

Cover Shape Circular Cover Bearing Surface Diameter Width
Cover Size 23.3 in Cover Bearing Surface Diameter 23.0 in
Civer Size Width # Vent Holes
Cover Material Cast Iron Vent Hole Diameter
Cover Frame Fit Good
Cover Type
☒ Solid ☐ Bolted
☐ Vented/Slots ☐ Locking
☐ Gasketed ☐ Lamphole
☐ Hatch Single ☐ Inner Cover
☐ Hatch Double
Cover Condition
☒ Solid ☐ Missing
☐ Cracked ☐ Corroded/Pitted
☐ Broken ☐ Bolts Missing
☐ Restraint Missing
☐ Restraint Defective

Cover Insert

Cover Insert Type None Cover Insert Condition
☐ Solid ☐ Leaking
☐ Poorly Fitting ☐ Corroded
☐ Cracked/Torn/Holes ☐ Insert Fell

Sheet 1362

Survey Date 20250715

P.O. No

Location (No. & Name) 12971 E 32nd St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition☐ Sound☐ Cracked☐ Broken☐ Corroded/Pitted/Worn☐ Leaking☐ Poor Installation**Frame**

Frame Material Cast Iron

Frame Bearing Surface Width 0.8 in

Frame Bearing Surface Depth 1.0 in

Frame Clear Opening Diameter 21.8 in

Frame Offset Distance 0.0 in

Frame Depth

Frame Seal Inflow None

Frame Condition☒ Sound☐ Cracked☐ Broken☐ Missing☐ Corroded/Pitted/Worn☐ Coated**Frame Seal Condition**☐ Sound☐ Cracked☐ Broken☒ Loose/Not Attached☐ Offset**Chimney**

Chimney Material 1 Other

Chimney Material 2

Chimney Clear Opening

Chimney Depth 0.0 in

Interior Chimney Coating/Liner None - No Coating

Exterior Chimney Coating/Liner

Chimney I/I

Cone

Cone Type Conical centered

Exterior Cone Coating/Liner

Interior Cone Coating/Liner

Cone Depth 3.2 in

Cone Material Brick

Wall

Wall Diameter 1 48

Wall Diameter 2

Wall Material Brick

Wall Depth 6.2 in

Interior Wall Coating/Liner Cementitious

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material Concrete (reinforced)

Channel Type Concrete (reinforced)

Channel Exposure F

Channel Installed Y

Step

Steps 3

Step Material Metal

Sheet 1362

Survey Date 20250715

P.O. No

Location (No. & Name) 12971 E 32nd St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	6.8	O	VCP	C	8	8	S	D	GR	080-0374:080-0373
	Mainline		Comments								
2	9	6.7	I	VCP	C	8	8	D	D	GR	080-0375:080-0374
	Mainline		Comments								
3	11	6.5	I	VCP	C	8	8	D	D	GR	080-0378:080-0374
	Mainline		Comments								

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
2.3 ft	COI	VC									360-0.0
	Remarks										
5.9 ft	WI	FC							12	12	360-0.0
	Remarks										
5.9 ft	WI	FC							10	12	360-0.0
	Remarks Pipe seal										
5.9 ft	WI	FC							8	10	360-0.0
	Remarks Pipe seal										
5.9 ft	WI	FC							5	7	360-0.0
	Remarks Pipe seal										
6.2 ft	B	DSF				10			12	12	360-0.0
	Remarks										