

**Sheet** 1377    **Surveyor's Name** Caleb Lyda    **Certificate Number** P0053047-032025    **Date** 20250714  
**System Owner**    **Survey Customer**    **Time** 15:14  
**Drainage Area**    **Locality/City Name** Tulsa  
**P.O. No**    **Location (No. & Name)** 3171 S 129th East Ave  
**Further Location Details**    **Inspection Level** Level 2  
**Outgoing Rim to Invert** 4.9 ft    **Outgoing Grade to Invert** 4.6 ft    **Rim to Grade** 0.3 ft  
**Use of Sewer** Sanitary    **Year Laid**    **Year Rehabilitated**    **Media Label**  
**Purpose** Sewer System Evaluation Survey    **Sewer Category**  
**Pre-Cleaning** No Pre-Cleaning    **Date Cleaned**    **Weather**  
**Location Code** Yard    **Potential for Runoff**    **Evidence of Surcharge** Yes  
**Access Point Type** Other Special Chamber    **Coordinate System** WGS 1984  
**Northing** 36.1153    **Easting** -95.8322    **Elevation**    **Accuracy of GPS**  
**Inspection Status** Remote Inspection  
**Additional Information** No chimney, no cone, no bench, channel is VCP, large separation at frame seal, no evidence of infil noticed

**Node Surface Types**

**Concrete Pavement** ☐    **Concrete Collar** ☐    **Asphalt** ☐    **Grass / Dirt** ☒    **Gravel** ☐    **Other** ☐

**Cover**

**Cover Shape** Circular    **Cover Bearing Surface Diameter Width**  
**Cover Size** 11.3 in    **Cover Bearing Surface Diameter** 11.0 in  
**Cover Size Width**    **# Vent Holes**  
**Cover Material** Cast Iron    **Vent Hole Diameter**  
**Cover Frame Fit** Good

**Cover Type**

☒ **Solid**    ☐ **Bolted**  
☐ **Vented/Slots**    ☐ **Locking**  
☐ **Gasketed**    ☐ **Lamphole**  
☐ **Hatch Single**    ☐ **Inner Cover**  
☐ **Hatch Double**

**Cover Condition**

☒ **Solid**    ☐ **Missing**  
☐ **Cracked**    ☐ **Corroded/Pitted**  
☐ **Broken**    ☐ **Bolts Missing**  
☐ **Restraint Missing**  
☐ **Restraint Defective**

**Cover Insert**

**Cover Insert Type** None

**Cover Insert Condition**

☐ **Solid**    ☐ **Leaking**  
☐ **Poorly Fitting**    ☐ **Corroded**  
☐ **Cracked/Torn/Holes**    ☐ **Insert Fell**

Sheet 1377

Survey Date 20250714

P.O. No

Location (No. &amp; Name) 3171 S 129th East Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**

- |                                  |   |
|----------------------------------|---|
| <input type="checkbox"/> Sound   | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking              |
| <input type="checkbox"/> Broken  | <input type="checkbox"/> Poor Installation    |

**Frame**

Frame Material Cast Iron

Frame Offset Distance 1.5 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 9.0 in

**Frame Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing              |
| <input type="checkbox"/> Cracked          | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Coated               |

**Frame Seal Condition**

- |   |  |
|---|--|
| <input type="checkbox"/> Sound              | <input checked="" type="checkbox"/> Loose/Not Attached |
| <input checked="" type="checkbox"/> Cracked |  |
| <input type="checkbox"/> Broken             | <input checked="" type="checkbox"/> Offset             |

**Chimney**

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

**Cone**

Cone Type Flattop

Cone Depth 0.0 in

Exterior Cone Coating/Liner

Cone Material Other

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 9

Wall Depth 4.9 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Vitrified Clay

Exterior Wall Coating/Liner

**Bench**

Bench Present N

Bench Material Other

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Other

Channel Type Other

Channel Exposure F

Channel Installed Y

**Step**

# Steps 0

Step Material

Sheet 1377

Survey Date 20250714

P.O. No

Location (No. &amp; Name) 3171 S 129th East Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	4.9	O	VCP	C	8	8	D	S	GR	080-0396:080-0395
	Mainline		Comments								

**Observations**

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
1.5 ft	WI	DAZ				10			12	12	360-0.0
	Remarks		Surcharge evidence								
3.7 ft	WI	IS		Y					12	12	360-0.0
	Remarks										
3.7 ft	WI	JOM									360-0.0
	Remarks										