

Sheet 780	Surveyor's Name	Brian Kauppenin	Certificate Number	U-218-070300218	Date	20250321
System Owner			Survey Customer		Time	08:44
Drainage Area			Locality/City Name	Tulsa		
P.O. No			Location (No. & Name)	3700 S 146th E Ave		
Further Location Details			Inspection Level	Level 2		
Outgoing Rim to Invert	9.4 ft	Outgoing Grade to Invert	8.4 ft	Rim to Grade	1.0 ft	
Use of Sewer	Sanitary	Year Laid	Year Rehabilitated	Media Label		
Purpose	Sewer System Evaluation Survey		Sewer Category			
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	Weather			
Location Code	Easement/Right of Way	Potential for Runoff	Evidence of Surcharge	Yes		
Access Point Type	Manhole	Coordinate System				
Northing		Elevation	Accuracy of GPS			
Inspection Status	Remote Inspection					
Additional Information	No chimney					
Node Surface Types						

Concrete Pavement	<input type="checkbox"/>	Concrete Collar	<input type="checkbox"/>	Asphalt	<input type="checkbox"/>	Grass / Dirt	<input checked="" type="checkbox"/>	Gravel	<input type="checkbox"/>	Other	<input type="checkbox"/>
-------------------	--------------------------	-----------------	--------------------------	---------	--------------------------	--------------	-------------------------------------	--------	--------------------------	-------	--------------------------

Cover

Cover Shape	Circular	Cover Bearing Surface Diameter Width	
Cover Size	23.8 in	Cover Bearing Surface Diameter	23.5 in
Civer Size Width		# Vent Holes	
Cover Material	Cast Iron	Vent Hole Diameter	
Cover Frame Fit	Good		
Cover Type		Cover Condition	
<input checked="" type="checkbox"/> Solid	<input type="checkbox"/> Bolted	<input checked="" type="checkbox"/> Solid	<input type="checkbox"/> Missing
<input type="checkbox"/> Vented/Slots	<input type="checkbox"/> Locking	<input type="checkbox"/> Cracked	<input type="checkbox"/> Corroded/Pitted
<input type="checkbox"/> Gasketed	<input type="checkbox"/> Lamphole	<input type="checkbox"/> Broken	<input type="checkbox"/> Bolts Missing
<input type="checkbox"/> Hatch Single	<input type="checkbox"/> Inner Cover	<input type="checkbox"/> Restraint Missing	
<input type="checkbox"/> Hatch Double		<input type="checkbox"/> Restraint Defective	

Cover Insert

Cover Insert Type	None
-------------------	------

Cover Insert Condition

<input type="checkbox"/> Solid	<input type="checkbox"/> Leaking
<input type="checkbox"/> Poorly Fitting	<input type="checkbox"/> Corroded
<input type="checkbox"/> Cracked/Torn/Holes	<input type="checkbox"/> Insert Fell

Sheet 780

Survey Date 20250321

P.O. No

Location (No. & Name) 3700 S 146th E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

- | | |
|----------------------------------|---|
| <input type="checkbox"/> Sound | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Poor Installation |

Frame

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 22.5 in

Frame Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Coated |

Frame Seal Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked | |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Offset |

Chimney

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

Cone

Cone Type Flattop

Cone Depth 1.6 in

Exterior Cone Coating/Liner None - No Coating

Cone Material Concrete (reinforced)

Interior Cone Coating/Liner None - No Coating

Wall

Wall Diameter 1 48

Wall Depth 8.8 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Concrete (reinforced)

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material Concrete (reinforced)

Channel Type Concrete (reinforced)

Channel Exposure F

Channel Installed Y

Step

Steps 5

Step Material Plastic

Sheet 780

Survey Date 20250321

P.O. No

Location (No. & Name) 3700 S 146th E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk Pos	Rim to Invert	Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special Condition	PSR
1	6	9.4	O	DIP	C	8		S	S	GR	Auto Pipe 1034C
	Mainline		Comments								
2	9	9.3	I	DIP	C	8		S	S	GR	Auto Pipe 1035C
	Mainline		Comments								
3	12	9.2	I	PVC	C	8		S	S	GR	Auto Pipe 1036C
	Mainline		Comments								

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
6.2 ft	WI	IS							8		360-0.0
	Remarks										
8.1 ft	WI	MGO									360-0.0
	Remarks		Water mark								
8.9 ft	B	DSZ				5			12	12	360-0.0
	Remarks		Toilet paper and sludge								