

| | | | |
|--|---------------------------------|---------------------------------------|-----------------|
| Sheet 1352 | Surveyor's Name Ian McInnis | Certificate Number P0039757-102022 | Date 20250513 |
| System Owner | | Survey Customer | Time 10:46 |
| Drainage Area | | Locality/City Name Tusla | |
| P.O. No | | Location (No. & Name) 12513 E 15th Pl | |
| Further Location Details | | Inspection Level Level 2 | |
| Outgoing Rim to Invert 6.5 ft | Outgoing Grade to Invert 6.2 ft | Rim to Grade 0.3 ft | |
| Use of Sewer Sanitary | Year Laid | Year Rehabilitated | Media Label |
| Purpose Sewer System Evaluation Survey | | Sewer Category | |
| Pre-Cleaning No Pre-Cleaning | Date Cleaned | Weather | |
| Location Code Yard | Potential for Runoff | Evidence of Surcharge No | |
| Access Point Type Manhole | Coordinate System | | |
| Northing | Easting | Elevation | Accuracy of GPS |
| Inspection Status Remote Inspection | | | |
| Additional Information No chimney | | | |
| Node Surface Types | | | |

| | | | | | | | | | | | |
|-------------------|--------------------------|-----------------|--------------------------|---------|--------------------------|--------------|-------------------------------------|--------|--------------------------|-------|--------------------------|
| Concrete Pavement | <input type="checkbox"/> | Concrete Collar | <input type="checkbox"/> | Asphalt | <input type="checkbox"/> | Grass / Dirt | <input checked="" type="checkbox"/> | Gravel | <input type="checkbox"/> | Other | <input type="checkbox"/> |
|-------------------|--------------------------|-----------------|--------------------------|---------|--------------------------|--------------|-------------------------------------|--------|--------------------------|-------|--------------------------|

Cover

| | | | |
|---|--------------------------------------|--|--|
| Cover Shape | Circular | Cover Bearing Surface Diameter Width | |
| Cover Size | 23.3 in | Cover Bearing Surface Diameter | 23.0 in |
| Civer Size Width | | # Vent Holes | |
| Cover Material | Cast Iron | Vent Hole Diameter | |
| Cover Frame Fit | Good | | |
| Cover Type | | Cover Condition | |
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Bolted | <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Vented/Slots | <input type="checkbox"/> Locking | <input type="checkbox"/> Cracked | <input type="checkbox"/> Corroded/Pitted |
| <input type="checkbox"/> Gasketed | <input type="checkbox"/> Lamphole | <input type="checkbox"/> Broken | <input type="checkbox"/> Bolts Missing |
| <input type="checkbox"/> Hatch Single | <input type="checkbox"/> Inner Cover | <input type="checkbox"/> Restraint Missing | |
| <input type="checkbox"/> Hatch Double | | <input type="checkbox"/> Restraint Defective | |

Cover Insert

| | |
|-------------------|------|
| Cover Insert Type | None |
|-------------------|------|

Cover Insert Condition

| | |
|---|--------------------------------------|
| <input type="checkbox"/> Solid | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Poorly Fitting | <input type="checkbox"/> Corroded |
| <input type="checkbox"/> Cracked/Torn/Holes | <input type="checkbox"/> Insert Fell |

Sheet 1352

Survey Date 20250513

P.O. No

Location (No. & Name) 12513 E 15th Pl

Inspection Level Level 2

Locality/City Name Tusla

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

- | | |
|----------------------------------|---|
| <input type="checkbox"/> Sound | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Poor Installation |

Frame

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 21.8 in

Frame Condition

- | | |
|----------------------------------|--|
| <input type="checkbox"/> Sound | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Cracked | <input checked="" type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Coated |

Frame Seal Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked | |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Offset |

Chimney

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

Cone

Cone Type Conical centered

Cone Depth 3.2 in

Exterior Cone Coating/Liner

Cone Material Brick

Interior Cone Coating/Liner

Wall

Wall Diameter 1 45

Wall Depth 6.1 in

Wall Diameter 2

Interior Wall Coating/Liner Cementitious

Wall Material Brick

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Brick

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material Concrete (non-reinforced)

Channel Type Concrete (non-reinforced)

Channel Exposure F

Channel Installed Y

Step

Steps 3

Step Material Plastic

Sheet 1352

Survey Date 20250513

P.O. No

Location (No. & Name) 12513 E 15th Pl

Inspection Level Level 2

Locality/City Name Tusla

Inspection Status Remote Inspection

Pipe Connections

| Num | Clk | Rim to Pos | Invert | Direc | Material | Shape | Diam | Width | Pipe Cond | Seal Cond | Special Condition | PSR |
|-----|----------|------------|--------|----------|----------|-------|------|-------|-----------|-----------|-------------------|--------------|
| 1 | 6 | 6.5 | | O | VCP | C | 8 | | D | S | GR | Auto Pipe 17 |
| | Mainline | | | Comments | | | | | | | | |
| 2 | 3 | 6.4 | | I | VCP | C | 8 | | S | S | GR | Auto Pipe 18 |
| | Mainline | | | Comments | | | | | | | | |

Observations

| Distance | Comp | Code | CD | Jnt | Stp | % | In1 | In2 | Fr | To | Video Reference |
|----------|--|------|----|-----|-----|----|-----|-----|----|----|-----------------|
| 1.0 ft | COI | ISSR | | | | 5 | | | 4 | 5 | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 3.2 ft | COI | IS | | | | | | | 9 | 1 | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 3.8 ft | WI | IS | | | | | | | 11 | | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 5.1 ft | WI | FC | | | | | | | 2 | 3 | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 5.1 ft | WI | IS | | | | | | | 2 | 3 | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 5.9 ft | WI | IS | | | | | | | 4 | | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 6.1 ft | B | DSZ | | | | 10 | | | 12 | 12 | 360-0.0 |
| | Remarks Appears to be dirt and external debris | | | | | | | | | | |