

Sheet 1399    Surveyor's Name Nicolas Ramon    Certificate Number P0051435-122024    Date 20250620  
System Owner    Survey Customer    Time 10:41  
Drainage Area    Locality/City Name Tulsa  
P.O. No    Location (No. & Name) 11511 E 17th Pl  
Further Location Details    Inspection Level Level 2  
Outgoing Rim to Invert 4.7 ft    Outgoing Grade to Invert 4.7 ft    Rim to Grade 0.0 ft  
Use of Sewer Sanitary    Year Laid    Year Rehabilitated    Media Label  
Purpose Sewer System Evaluation Survey    Sewer Category  
Pre-Cleaning No Pre-Cleaning    Date Cleaned    Weather  
Location Code Yard    Potential for Runoff    Evidence of Surge No  
Access Point Type Other Special Chamber    Coordinate System WGS 1984  
Northing 36.1379    Easting -95.849    Elevation    Accuracy of GPS  
Inspection Status Remote Inspection  
Additional Information No chimney, no cone, no bench, channel is VCP  
Node Surface Types

Concrete Pavement ☐    Concrete Collar ☐    Asphalt ☐    Grass / Dirt ☒    Gravel ☐    Other ☐

**Cover**

Cover Shape Circular    Cover Bearing Surface Diameter Width  
Cover Size 11.3 in    Cover Bearing Surface Diameter 11.0 in  
Civer Size Width    # Vent Holes  
Cover Material Cast Iron    Vent Hole Diameter  
Cover Frame Fit Good  
Cover Type  
☒ Solid    ☐ Bolted  
☐ Vented/Slots    ☐ Locking  
☐ Gasketed    ☐ Lamphole  
☐ Hatch Single    ☐ Inner Cover  
☐ Hatch Double  
Cover Condition  
☒ Solid    ☐ Missing  
☐ Cracked    ☐ Corroded/Pitted  
☐ Broken    ☐ Bolts Missing  
☐ Restraint Missing  
☐ Restraint Defective

**Cover Insert**

Cover Insert Type None

**Cover Insert Condition**

☐ Solid    ☐ Leaking  
☐ Poorly Fitting    ☐ Corroded  
☐ Cracked/Torn/Holes    ☐ Insert Fell

Sheet 1399

Survey Date 20250620

P.O. No

Location (No. &amp; Name) 11511 E 17th Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**☐ Sound☐ Corroded/Pitted/Worn☐ Cracked☐ Leaking☐ Broken☐ Poor Installation**Frame**

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 1.3 in

Frame Depth

Frame Bearing Surface Depth 0.5 in

Frame Seal Inflow None

Frame Clear Opening Diameter 9.5 in

**Frame Condition**☒ Sound☐ Missing☐ Cracked☐ Corroded/Pitted/Worn☐ Broken☐ Coated**Frame Seal Condition**☒ Sound☐ Loose/Not Attached☐ Cracked☐ Broken☐ Offset**Chimney**

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

**Cone**

Cone Type Flattop

Cone Depth 0.0 in

Exterior Cone Coating/Liner

Cone Material Other

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 8

Wall Depth 4.7 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Vitrified Clay

Exterior Wall Coating/Liner

**Bench**

Bench Present N

Bench Material Other

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Other

Channel Type Other

Channel Exposure F

Channel Installed Y

**Step**

# Steps 0

Step Material

Sheet 1399

Survey Date 20250620

P.O. No

Location (No. &amp; Name) 11511 E 17th Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	4.7	O	VCP	C	8	8	D	S	GR	082-0220:082-0217
	Mainline		Comments								

**Observations**

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
0.9 ft	WI	FM		Y					12	12	360-0.0
	Remarks										
1.0 ft	WI	FM		Y					12	12	360-0.0
	Remarks										