

Sheet 624 Surveyor's Name Brian Kauppenin Certificate Number U-218-070300218 Date 20250307
System Owner Survey Customer Time 13:11
Drainage Area Locality/City Name Tulsa
P.O. No Location (No. & Name) 12101 E 23rd St
Further Location Details Inspection Level Level 2
Outgoing Rim to Invert 5.5 ft Outgoing Grade to Invert 5.5 ft Rim to Grade 0.0 ft
Use of Sewer Sanitary Year Laid Year Rehabilitated Media Label
Purpose Sewer System Evaluation Survey Sewer Category
Pre-Cleaning No Pre-Cleaning Date Cleaned Weather
Location Code Yard Potential for Runoff Evidence of Surcharge Yes
Access Point Type Manhole Coordinate System
Northing Easting Elevation Accuracy of GPS
Inspection Status Remote Inspection
Additional Information
Node Surface Types

Concrete Pavement ☐ Concrete Collar ☐ Asphalt ☐ Grass / Dirt ☒ Gravel ☐ Other ☐

Cover

Cover Shape Circular Cover Bearing Surface Diameter Width
Cover Size 23.3 in Cover Bearing Surface Diameter 23.0 in
Civer Size Width # Vent Holes
Cover Material Cast Iron Vent Hole Diameter
Cover Frame Fit Good
Cover Type
☒ Solid ☐ Bolted
☐ Vented/Slots ☐ Locking
☐ Gasketed ☐ Lamphole
☐ Hatch Single ☐ Inner Cover
☐ Hatch Double
Cover Condition
☒ Solid ☐ Missing
☐ Cracked ☐ Corroded/Pitted
☐ Broken ☐ Bolts Missing
☐ Restraint Missing
☐ Restraint Defective

Cover Insert

Cover Insert Type None

Cover Insert Condition

☐ Solid ☐ Leaking
☐ Poorly Fitting ☐ Corroded
☐ Cracked/Torn/Holes ☐ Insert Fell

Sheet 624

Survey Date 20250307

P.O. No

Location (No. & Name) 12101 E 23rd St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type Solid

Adjustment Ring Material Cast Iron

Adjustment Ring Height

Adjustment Ring Condition

☒ **Sound** ☐ **Corroded/Pitted/Worn**

☐ **Cracked** ☐ **Leaking**

☐ **Broken** ☐ **Poor Installation**

Frame

Frame Material Cast Iron

Frame Bearing Surface Width 0.8 in

Frame Bearing Surface Depth 1.0 in

Frame Clear Opening Diameter 21.8 in

Frame Offset Distance 0.0 in**Frame Depth****Frame Seal Inflow** None**Frame Condition**

☒ **Sound** ☐ **Missing**

☐ **Cracked** ☐ **Corroded/Pitted/Worn**

☐ **Broken** ☐ **Coated**

Frame Seal Condition

☒ **Sound** ☐ **Loose/Not Attached**

☐ **Cracked**

☐ **Broken** ☐ **Offset**

Chimney

Chimney Material 1 Brick

Chimney Material 2

Chimney Clear Opening

Chimney Depth 1.3 in

Interior Chimney Coating/Liner Cementitious**Exterior Chimney Coating/Liner****Chimney I/I****Cone**

Cone Type Conical centered

Exterior Cone Coating/Liner

Interior Cone Coating/Liner

Cone Depth 3.5 in**Cone Material** Brick**Wall**

Wall Diameter 1 49

Wall Diameter 2

Wall Material Brick

Wall Depth 5.1 in**Interior Wall Coating/Liner** Cementitious**Exterior Wall Coating/Liner****Bench**

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material Concrete (non-reinforced)

Channel Type Concrete (non-reinforced)

Channel Exposure F

Channel Installed Y

Step

Steps 2

Step Material Plastic

Sheet 624

Survey Date 20250307

P.O. No

Location (No. & Name) 12101 E 23rd St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	5.3	O	VCP	C	8		S	D	GR	Auto Pipe 666C
	Mainline		Comments								

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
4.9 ft	WI	CC							12	12	360-0.0
	Remarks	Includes pipe seal 1									
4.9 ft	WI	RFB							3	4	360-0.0
	Remarks										
5.2 ft	B	DSF				5			12	12	360-0.0
	Remarks										