

Sheet 1255    Surveyor's Name Nicolas Ramon    Certificate Number P0051435-122024    Date 20250407  
System Owner    Survey Customer    Time 09:26  
Drainage Area    Locality/City Name Tulsa  
P.O. No    Location (No. & Name) 12822 E 24th Pl  
Further Location Details    Inspection Level Level 2  
Outgoing Rim to Invert 4.9 ft    Outgoing Grade to Invert 4.9 ft    Rim to Grade 0.0 ft  
Use of Sewer Sanitary    Year Laid    Year Rehabilitated    Media Label  
Purpose Sewer System Evaluation Survey    Sewer Category  
Pre-Cleaning No Pre-Cleaning    Date Cleaned    Weather  
Location Code Yard    Potential for Runoff    Evidence of Surcharge No  
Access Point Type Other Special Chamber    Coordinate System  
Northing    Easting    Elevation    Accuracy of GPS  
Inspection Status Remote Inspection  
Additional Information No chimney, no cone, no bench, channel is VCP  
Node Surface Types

Concrete Pavement ☐    Concrete Collar ☐    Asphalt ☐    Grass / Dirt ☒    Gravel ☐    Other ☐

**Cover**

Cover Shape Circular    Cover Bearing Surface Diameter Width  
Cover Size 11.3 in    Cover Bearing Surface Diameter 11.0 in  
Civer Size Width    # Vent Holes  
Cover Material Cast Iron    Vent Hole Diameter  
Cover Frame Fit Good  
Cover Type  
☒ Solid    ☐ Bolted  
☐ Vented/Slots    ☐ Locking  
☐ Gasketed    ☒ Lamphole  
☐ Hatch Single    ☐ Inner Cover  
☐ Hatch Double  
Cover Condition  
☒ Solid    ☐ Missing  
☐ Cracked    ☐ Corroded/Pitted  
☐ Broken    ☐ Bolts Missing  
☐ Restraint Missing  
☐ Restraint Defective

**Cover Insert**

Cover Insert Type None    Cover Insert Condition  
☐ Solid    ☐ Leaking  
☐ Poorly Fitting    ☐ Corroded  
☐ Cracked/Torn/Holes    ☐ Insert Fell

Sheet 1255

Survey Date 20250407

P.O. No

Location (No. &amp; Name) 12822 E 24th Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**

- |                                  |   |
|----------------------------------|---|
| <input type="checkbox"/> Sound   | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking              |
| <input type="checkbox"/> Broken  | <input type="checkbox"/> Poor Installation    |

**Frame**

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 1.3 in

Frame Depth

Frame Bearing Surface Depth 0.5 in

Frame Seal Inflow None

Frame Clear Opening Diameter 9.5 in

**Frame Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing              |
| <input type="checkbox"/> Cracked          | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Coated               |

**Frame Seal Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked          |   |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Offset             |

**Chimney**

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

**Cone**

Cone Type Flattop

Cone Depth 0.0 in

Exterior Cone Coating/Liner

Cone Material Other

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 8

Wall Depth 4.9 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Vitrified Clay

Exterior Wall Coating/Liner

**Bench**

Bench Present N

Bench Material Other

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Other

Channel Type Other

Channel Exposure F

Channel Installed Y

**Step**

# Steps 0

Step Material

Sheet 1255

Survey Date 20250407

P.O. No

Location (No. &amp; Name) 12822 E 24th Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	4.9	O	VCP	C	8	8	D	S	GR	082-0566:082-0565
	Mainline			Comments							