

Sheet 1434 Surveyor's Name BK

Certificate Number U-218-070300218

Date 20251209

System Owner

Survey Customer

Time 07:44

Drainage Area

Locality/City Name Tulsa

P.O. No

Location (No. & Name) 801 Mingo Rd

Further Location Details

Inspection Level Level 2

Outgoing Rim to Invert 23.6 ft

Outgoing Grade to Invert 17.7 ft

Rim to Grade 5.9 ft

Use of Sewer Sanitary

Year Laid

Year Rehabilitated

Media Label

Purpose Sewer System Evaluation Survey

Sewer Category

Pre-Cleaning No Pre-Cleaning

Date Cleaned

Weather

Location Code Easement/Right of Way

Potential for Runoff

Evidence of Surcharge Yes

Access Point Type Manhole

Coordinate System

Northing

Easting

Elevation

Accuracy of GPS

Inspection Status Remote Inspection

Additional Information No chimney - wall is rectangular

Node Surface Types

Concrete Pavement ☐Concrete Collar ☐Asphalt ☐Grass / Dirt ☒Gravel ☐Other ☐**Cover**

Cover Shape Circular

Cover Bearing Surface Diameter Width

Cover Size 32.0 in

Cover Bearing Surface Diameter 31.8 in

Civer Size Width

Vent Holes

Cover Material Plastic/Steel

Vent Hole Diameter

Cover Frame Fit Composite
Good

Cover Type

- | | |
|--|---|
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Bolted |
| <input type="checkbox"/> Vented/Slots | <input checked="" type="checkbox"/> Locking |
| <input checked="" type="checkbox"/> Gasketed | <input type="checkbox"/> Lamphole |
| <input type="checkbox"/> Hatch Single | <input type="checkbox"/> Inner Cover |
| <input type="checkbox"/> Hatch Double | |

Cover Condition

- | | |
|--|--|
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Corroded/Pitted |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Bolts Missing |
| <input type="checkbox"/> Restraint Missing | |
| <input type="checkbox"/> Restraint Defective | |

Cover Insert

Cover Insert Type None

Cover Insert Condition

- | | |
|---|--------------------------------------|
| <input type="checkbox"/> Solid | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Poorly Fitting | <input type="checkbox"/> Corroded |
| <input type="checkbox"/> Cracked/Torn/Holes | <input type="checkbox"/> Insert Fell |

Sheet 1434

Survey Date 20251209

P.O. No

Location (No. & Name) 801 Mingo Rd

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

- | | |
|----------------------------------|---|
| <input type="checkbox"/> Sound | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Poor Installation |

Frame

Frame Material Plastic/Steel Composite

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.3 in

Frame Seal Inflow None

Frame Clear Opening Diameter 30.3 in

Frame Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Coated |

Frame Seal Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked | |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Offset |

Chimney

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

Cone

Cone Type Flattop

Cone Depth 0.6 in

Exterior Cone Coating/Liner

Cone Material Concrete (reinforced)

Interior Cone Coating/Liner

Wall

Wall Diameter 1 96

Wall Depth 21.6 in

Wall Diameter 2 72

Interior Wall Coating/Liner None - No Coating

Wall Material Concrete (reinforced)

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material	Concrete (reinforced)
Channel Type	Concrete (reinforced)
Channel Exposure	F
Channel Installed	Y

Step

# Steps	10
Step Material	Metal

Sheet 1434

Survey Date 20251209

P.O. No

Location (No. & Name) 801 Mingo Rd

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk	Rim to Pos	Invert	Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special Condition	PSR
1	6	23.6		O	DIP	C	12		D	S	GR	Auto Pipe 48AA
	Mainline		Comments									
2	12	23.5		I	DIP	C	10		D	S	GR	Auto Pipe 49AA
	Mainline		Comments									
3	1	23.5		I	DIP	C	10		D	S	GR	Auto Pipe 50AA
	Mainline		Comments									

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
6.6 ft	WI	MGO									
	Remarks		Top of structure has been replaced								
15.7 ft	WI	DAZ				5			10		
	Remarks		Toilet paper								
16.0 ft	WI	MSC					48	96			
	Remarks		4x4 to 6x8								
18.0 ft	WI	DAZ				5			11		
	Remarks		Toilet paper								
21.7 ft	B	DSC				5			12	12	
	Remarks										
21.8 ft	B	OBP				5			2		
	Remarks										
21.8 ft	B	OBP				5			8		
	Remarks										
22.2 ft	B	SRI							12	1	
	Remarks										