

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 19 Moore's Run

Site Name:	19_MR81I	Monitor Series:	4000	Monitor S/N:	1141	Manhole #:	MR81	Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: MR80 Downstream Manhole: MR82 Air DOF: 11" Description of Site Hydraulics: No abnormal flow conditions were observed.
Address / Location:	5319 Todd Ave	Map Page #:	10	Map Grid #:	67YY			
		Pipe Height:	30"	Pipe Width:	30"			
		IP Address:	166.142.228.123					
Access:	Drive	GPS Coords:	N DD.dddd		W DD.dddd			
			39 19.728		76 32.331			
Date/Time of Investigation:	5/30/2003 12:25							

Access Map

Plan View

Manhole Information:

Manhole Depth:

Manhole Material / Condition:
Brick / Good

Active Drop Connections?
No

System Character:

☒ Residential
☐ Commercial
☐ Industrial

Notes:

Odd Shape Pipe

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale

Elevation

Top View

The monitoring period ended as of February 28, 2005.