

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Defective

Address: 242 Hobson Ave

Basin: **HS62**

Segment (US : DS): **1268:1267**


Intensity: **High**

Drainage Area (SF): **10**

Surface: **Paved**

Comments:

QC Comments: confirm where cleanout defect is - possibly above grade and 0 drainage area - CP



Cleanout, Defective

Address: 234 Golf Links Rd

Basin: **HS45**

Segment (US : DS): **2066:2065**

Intensity: **Medium**

Drainage Area (SF): **25**

Surface: **Unpaved**

Comments:

QC Comments: Defect not clearly visible, revisit and take additional photo showing defective cleanout

