

30-3676-04: Tulsa Metropolitan Utility Authority (TMUA) FY26 On-Call

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 9607 E 25th St

Basin: **83-N**

Segment (US : DS): **083-0169:083-0168**


Intensity: **Low**

Drainage Area (SF): **200**

Surface: **Unpaved**

Comments:

QC Comments: Verify defect add to next biweekly



Cleanout, Missing/Broken Cap

Address: 10133 E 33rd St

Basin: **83-N**

Segment (US : DS): **083-0255:083-0253**

Intensity: **High**

Drainage Area (SF): **300**

Surface: **Paved**

Comments: *Smoking area*

QC Comments: Verify defect add to next biweekly

