

# Baltimore SSO

## Site Investigation Report

FM Initials: DF

Project: 02 Upper Jones Falls

Site Name:	02_34S	Monitor Series:	4000	Monitor S/N:	1140	Manhole #:	JP17	<b>Investigation Information:</b> Upstream Input: (L/S, P/S) N/A Upstream Manhole: JP16 Downstream Manhole: JP18 Depth of Flow: 21.25" Description of Site Hydraulics:  No abnormal conditons were observed.
Address / Location:	Cottonworth Ave	Map Page #:	2	Map Grid #:	19CC <sub>2</sub>			
		Pipe Height:	42"	Pipe Width:	42"			
		IP Address:	166.142.224.66					
Access:	Walk (Commercial)	GPS Coords:	N DD.dddd 39 21.885		W DD.dddd 76 38.955			
Date/Time of Investigation:	4/25/2003 0:00							

N Plan View

**Manhole Information:**

Manhole Depth: 14'3"

Manhole Material / Condition:  
Brick / Good

Active Drop Connections?  
No

System Character:

Residential

☒ Commercial

Industrial

Elevation

N Top View

**Notes:**

**Legend:**

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale

The monitoring period ended as of December 31, 2004.