



<b>Investigation Information:</b>	
Upstream Input: (L/S, P/S)	
Upstream Manhole: GR134	
Downstream Manhole: GR136	
Depth of Flow: 17"	
Description of Site Hydraulics:	
	Smooth, very fast
<b>Manhole Information:</b>	
Manhole Depth: 17'	
Manhole Material/Condition:	Brick/fair
Active Drop Connections?	No
<b>System Character:</b>	
	Residential
<b>X</b>	Commercial
	Industrial
<b>Notes:</b>	
	Night or early morning install
<b>Legend:</b>	
	<b>Cast Iron Flap Valve</b>
	<b>Sensor Location</b>
<b>N.T.S.- Not to scale</b>	

The monitoring period ended as of February 28, 2005.