

# Baltimore SSO

## Site Investigation Report

FM Initials: DF

Project Number: 09 Gwynns Run Interceptor

Site Name:	09_GR85I	Monitor Series:	4000	Monitor S/N:	1133	Manhole #:	86	<b>Investigation Information:</b> Upstream Input: P/S Ashburton Upstream Manhole: GR84 Downstream Manhole: GR86 Depth of Flow: 7.75" +/- .5 Description of Site Hydraulics:  Fast flow; fairly smooth.
Address / Location:	Hanlon Park straight down from swingset	Map Page #:		Pipe Height:	20"	Pipe Width:	20"	
		IP Address:	166.142.224.164					
		GPS Coords:	N DD.dddd 39 18.924		W DD.dddd 76 39.960			
Access:	Drive							
Date/Time of Investigation:	8/20/2003 11:30							

Plan View

**Manhole Information:**  
 Manhole Depth: 10'  
 Manhole Material/Condition:  
 Concrete / Fair  
 Active Drop Connections?  
 No

Elevation

Top View

**System Character:**  
 Residential  
☒ Commercial  
☒ Industrial

**Notes:**  
  
**Legend:**  
 Cast Iron Flap Valve  
 Sensor Location  
 N.T.S.- Not to scale

The monitoring period ended as of February 28, 2005.