

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 15 Maiden's Choice Interceptor

| | | | | | | | | |
|-----------------------------|----------------------------------|-----------------|-----------------|--------------|-----------|------------|-------|--|
| Site Name: | 15_24PSA | Monitor Series: | 4000 | Monitor S/N: | | Manhole #: | MCF12 | Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: MCF11 Downstream Manhole: MC6 Depth of Flow: 3.5" +/- 0.5" Description of Site Hydraulics: No abnormal conditions |
| Address / Location: | Mallow Hill Rd and Frederick Ave | Map Page #: | 11 | Map Grid #: | 60 | | | |
| | | Pipe Height: | 14.13" | Pipe Width: | 14" | | | |
| | | IP Address: | 166.142.225.209 | | | | | |
| Access: | Walk (Residential) | GPS Coords: | N DD.dddd | | W DD.dddd | | | |
| | | | 39 16.735 | | 76 42.534 | | | |
| Date/Time of Investigation: | 10/28/05 14:00 | | | | | | | |

Access Map

N Plan View

Elevation

N Top View

Manhole Information:

Manhole Depth: 12'

Manhole Material / Condition:
Brick / Good

Active Drop Connections?
No

System Character:

☒ Residential
☐ Commercial
☐ Industrial

Notes:

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale

The monitoring period ended as of November 30, 2006.