

Baltimore SSO # 72

Site Investigation Report

FM Initials: TM

Project: 07 Greenmount Interceptor

Site Name:	P7_08_72S	Monitor Series:	Flow Shark	Monitor S/N:	16185	Manhole #:	S37GG_007MH	Investigation Information:
Address / Location:	Warehouse at Greenmount & Preston	Map Page #:	4818	Map Grid #:	C2			
		Pipe Height:	21"	Pipe Width:	21"			
Access:	Drive	GPS Coords:	X	Y				
			361540	4351668				
Date/Time of Investigation:	6/29/2005 10:30							

Plan View

Manhole Information:

Manhole Depth: 11.55'

Manhole Material / Condition:
BRICK - GOOD

Active Drop Connections?
Yes

Elevation

Overflow Level 75"

Top View

System Character:

Residential
X Commercial
Industrial

Notes:
Depth sensors measure level above interceptor invert. Velocity sensor located in overflow pipe.

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale