

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 519 South Ave

Basin: **HS62**

Segment (US : DS): **1854:2425**

Intensity: **High**

Drainage Area (SF): **10**

Surface: **Unpaved**

Comments: *Lid could not screw on fully*

QC Comments: Possible above grade - EE



Cleanout, Missing/Broken Cap

Address: 524 South Ave

Basin: **HS62**

Segment (US : DS): **1853:1854**

Intensity: **Low**

Drainage Area (SF): **10**

Surface: **Unpaved**

Comments:

QC Comments: Possible above grade - EE

