

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 407 Whittington Ave

Basin: **HS15**

Segment (US : DS): **10843:12528**

Intensity: **High**

Drainage Area (SF): **50**

Surface: **Unpaved**

Comments:

QC Comments: Possible above grade - EE

