

Smoke Observation Summary

Cleanout, Defective

Address: 4302 E Pine St

Basin: **CC-TL1415C**

Segment (US : DS): **094-0451:094-0450**

Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

QC Comments: retake close up that shows defect

