

30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

Smoke Observation Summary

Cleanout, Defective

Address: 829 N Delaware Ave

Basin: **CC-11**

Segment (US : DS): **030-0652:030-0249**

Intensity: **Low**

Drainage Area (SF): **500**

Surface: **Unpaved**

Comments:

QC Comments: retake close up showing/confirming defect

