

30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 1046 N College Ave

Basin: **CC-11**

Segment (US : DS): **030-0665:030-0255**


Intensity: **Low**

Drainage Area (SF): **200**

Surface: **Unpaved**

Comments:

QC Comments: Need area photo that shows drainage/roofline



Cleanout, Missing/Broken Cap

Address: 1024 N Delaware Pl

Basin: **CC-11**

Segment (US : DS): **030-0253:030-0252**

Intensity: **Low**

Drainage Area (SF): **150**

Surface: **Unpaved**

Comments:

QC Comments: confirm this is a CO - cannot see cleanout in photo, retake showing

