

## 30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

### Smoke Observation Summary

#### Cleanout, Missing/Broken Cap

Address: 1015 N Delaware Pl

Basin: **CC-11**

Segment (US : DS): **030-0262:030-0261**


Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

*QC Comments: retake area showing more area, not pointed down*



#### Cleanout, Defective

Address: 2739 E Latimer St

Basin: **CC-11**

Segment (US : DS): **030-0193:030-0192**

Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

*QC Comments: clarify where smoke is coming from*

