

## 30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

### Smoke Observation Summary

#### Cleanout, Defective

Address: 1110 N Gary Ave

Basin: **CC-11**

Segment (US : DS): **030-0119:030-0117**


Intensity: **Low**

Drainage Area (SF): **10**

Surface: **Unpaved**

Comments:

*QC Comments: retake area photo showing location, not pointing down - retake close up verifying defect*



#### Cleanout, Defective

Address: 1110 N Gary Ave

Basin: **CC-11**

Segment (US : DS): **030-0119:030-0117**

Intensity: **Low**

Drainage Area (SF): **30**

Surface: **Unpaved**

Comments:

*QC Comments: retake close up verifying defect, pull grass back*

