

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 4145 S 25th W Ave

Basin: **39-S**

Segment (US : DS): **039-0423:039-0422**


Intensity: **High**

Drainage Area (SF): **50**

Surface: **Unpaved**

Comments:

QC Comments: Need better roofline photo KR



Cleanout, Missing/Broken Cap

Address: 4208 S 24th W Ave

Basin: **39-S**

Segment (US : DS): **039-0423:039-0422**

Intensity: **High**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *Unknown info about cleanout. Grade and drainage area - homeowner refused access*

QC Comments: Homeowner refused access; need photo of something smoking

