

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 4147 S 26th W Ave

Basin: **39-S**
Segment (US : DS): **039-0411:039-0410**
Intensity: **High**
Drainage Area (SF): **0**
Surface: **Unpaved**
Comments: *Smoking area*
QC Comments: Verify threads



Cleanout, Defective

Address: 4141 S 24th E Ave

Basin: **39-S**
Segment (US : DS): **039-0547:039-0546**
Intensity: **Low**
Drainage Area (SF): **90**
Surface: **Unpaved**
Comments: *no access to backyard*
QC Comments: Need better close up to verify defect

