

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Defective

Address: 4511 S Vancouver Ave

Basin: **40-S**

Segment (US : DS): **040-0298:040-0297**


Intensity: **Medium**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

QC Comments: need FOH



Cleanout, Missing/Broken Cap

Address: 2134 W 45th Pl S

Basin: **40-S**

Segment (US : DS): **040-0189:040-0190**

Intensity: **High**

Drainage Area (SF): **100**

Surface: **Unpaved**

Comments: *Unable to access for closer pictures. No answer and gate was locked. Visible from neighbor's deckSmoking area*

QC Comments: Reattempt access for close up photo

