

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 4542 S 23rd West Ave

Basin: 40-S  
Segment (US : DS): 040-0186:040-0183  
Intensity: Low  
Drainage Area (SF): 0  
Surface: Unpaved  
Comments:  
*QC Comments: verify, possibly defective*

