

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Defective

Address: 1934 W 49th St S

Basin: 40-S

Segment (US : DS): 040-0248:040-0247

Intensity: Low

Drainage Area (SF): 100

Surface: Unpaved

Comments:

QC Comments: Verify defect KR

