

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Defective

Address: 1911 W 49th St

Basin: **40-S**

Segment (US : DS): **040-0241:040-0240**

Intensity: **Low**

Drainage Area (SF): **20**

Surface: **Unpaved**

Comments: *Gates locked no answer unable to get closer pictures dogs in backyard.*

QC Comments: Verify defect need defect in photo with flag
KR

